


- NOTES
1.  $\sqrt[125]{}$  SURFACE FINISH UNLESS  
OTHER WISE SPECIFIED.

PILOT No.	$\varnothing D_{10}$ -.003 -.001	$\varnothing D_{11}$ -.004 -.002	MATERIAL
-5001	.1635	.1635	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5002	.1885	.1885	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5003	.1885	.2490	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5004	.1885	.3110	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5005	.2490	.2490	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5006	.2490	.3110	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5007	.2490	.3740	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5008	.2490	.4365	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5009	.2490	.4990	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5010	.3740	.3740	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5011	.3740	.4365	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5012	.3740	.4990	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5013	.3740	.5615	4140 Q&T $\varnothing 5/8 \times 3-1/2$
-5014	.3740	.6240	4140 Q&T $\varnothing 5/8 \times 3-1/2$
-5015	.3740	.8740	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5016	.2490	.6240	4140 Q&T $\varnothing 5/8 \times 3-1/2$
-5017	.3740	.7490	4140 Q&T $\varnothing 3/4 \times 3-1/2$
-5018	.4990	.4990	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5019	.4990	.5615	4140 Q&T $\varnothing 5/8 \times 3-1/2$
-5020	.4990	.6240	4140 Q&T $\varnothing 5/8 \times 3-1/2$
-5021	.4990	.7490	4140 Q&T $\varnothing 3/4 \times 3-1/2$

PILOT No.	$\varnothing D_{10}$ -.003 -.001	$\varnothing D_{11}$ -.004 -.002	MATERIAL
-5022	.4990	.7864	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5023	.4990	.8740	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5024	.4990	.9990	4140 Q&T $\varnothing 1 \times 3-1/2$
-5025	.4990	1.1801	4140 Q&T $\varnothing 1-1/4 \times 3-1/2$
-5026	.4990	1.0615	4140 Q&T $\varnothing 1-1/8 \times 3-1/2$
-5027	.2490	.8740	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5028	.4990	1.2490	4140 Q&T $\varnothing 1-1/4 \times 3-1/2$
-5029	.4990	1.3120	4140 Q&T $\varnothing 1-3/8 \times 3-1/2$
-5030	.4990	1.4370	4140 Q&T $\varnothing 1-1/2 \times 3-1/2$
-5031	.4990	1.4990	4140 Q&T $\varnothing 1-1/2 \times 3-1/2$
-5032	.4990	2.0615	4140 Q&T $\varnothing 2-1/8 \times 3-1/2$
-5033	.4990	2.3115	4140 Q&T $\varnothing 2-3/8 \times 3-1/2$
-5034	.4990	2.4990	4140 Q&T $\varnothing 2-1/2 \times 3-1/2$
-5035	.4990	2.7490	4140 Q&T $\varnothing 2-3/4 \times 3-1/2$
-5036	.4990	1.5615	4140 Q&T $\varnothing 1-5/8 \times 3-1/2$
-5037	.4990	1.8120	4140 Q&T $\varnothing 1-7/8 \times 3-1/2$
-5038	.2490	.7490	4140 Q&T $\varnothing 3/4 \times 3-1/2$
-5039	.4990	1.7490	4140 Q&T $\varnothing 1-3/4 \times 3-1/2$
-5040	.4990	1.8740	4140 Q&T $\varnothing 1-7/8 \times 3-1/2$
-5041	.1240	.1240	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5042	.2490	.4990	4140 Q&T $\varnothing 1/2 \times 3-1/2$

PILOT No.	$\varnothing D_{10}$ -.003 -.001	$\varnothing D_{11}$ -.004 -.002	MATERIAL
-5043	.2490	.4830	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5044	.3740	.8740	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5045	.4990	1.4240	4140 Q&T $\varnothing 1-1/2 \times 3-1/2$
-5046	.4990	1.5940	4140 Q&T $\varnothing 1-5/8 \times 3-1/2$
-5047	.4990	2.0990	4140 Q&T $\varnothing 2-1/8 \times 3-1/2$
-5048	.1240	.2490	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5049	.1885	.3115	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5050	.1885	.3740	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5051	.1885	.4210	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5052	.1885	.4310	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5053	.1885	.4365	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5054	.1885	.4990	4140 Q&T $\varnothing 1/2 \times 3-1/2$
-5055	.2490	.6840	4140 Q&T $\varnothing 3/4 \times 3-1/2$
-5056	.2490	.8040	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5057	.4990	1.3730	4140 Q&T $\varnothing 1-3/8 \times 3-1/2$
-5058	.8740	.8740	4140 Q&T $\varnothing 7/8 \times 3-1/2$
-5059	.2490	.3140	4140 Q&T $\varnothing 3/8 \times 3-1/2$
-5060	.1885	.2352	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5061	.1885	.1958	4140 Q&T $\varnothing 1/4 \times 3-1/2$
-5062	.4990	1.4365	4140 Q&T $\varnothing 1-1/2 \times 3-1/2$
-5063	.6240	1.0628	4140 Q&T $\varnothing 1-1/8 \times 3-1/2$


<b>RED BARN MACHINE</b>	
TITLE 8 POINT STAKING TOOL; RETAINING RING	
DWG NO. RBST(TOOL# SEE Pg.1 CHART)-(PILOT# SEE CHART)-9	REV A
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON: DECIMALS .XXX $\pm$ .005 .XX $\pm$ .01 X $\pm$ .1	DRAWN BY: PERRITT APPROVED HEAT TREAT FINISH BLACK OXIDE SPEC USED ON BEARING SEE CHART Pg. 1
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	
SCALE NTS	DATE 2-14-08 SHEET 6 of 6



### NOTES

1. SAME PINS FOR ALL TOOL NUMBERS.
2. BREAK ALL SHARP EDGES.

ASSY QTY		ASSY QTY	B/O	PART #	UNIT QTY	DESCRIPTION	MAT.	B/O INFORMATION OR SPECIFICATIONS	RED BARN MACHINE	
			W/O	-7	8	PINS	STEEL	Ø.0625 MINUS GAUGE PIN MSC #8900625	TITLE 8 POINT STAKING TOOL; PIN	
									DWG NO. RBST(TOOL# 'SEE Pg.1 CHART)-(PILOT# SEE Pg.1 CHART)-7	
									UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	
									TOLERANCES ON:	
									DECIMALS .XXX ± .005	
									FRACTIONS ± 1/32	
									XX ± .01	
									X ± .1	
									UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R	
									2. DIMENSIONAL LIMITS APPLY AFTER PLATING	
									SCALE NTS	
									DATE 2-14-08	
									SHEET 5 of 6	




### NOTES


1. <sup>125</sup>✓ SURFACE FINISH UNLESS OTHER WISE SPECIFIED.
2. -5 HEIGHT IS .013 TO .014 LESS THAN -7 LENGTH.

TOOL #	PILOT No.	BEARING		ØD <sub>1</sub> +.0003 -.0008	ØD <sub>2</sub> +.005 -.005	ØD <sub>3</sub> +.015 -.000	MATERIAL
		OD.	ID.				
1312-055-8-GT	-5015	1.3125	.8750	1.2360	1.382	1.562	4140 Q&T Ø1-5/8 x 1/2

<b>RED BARN MACHINE</b>	
TITLE 8 POINT STAKING TOOL; RETAINING RING	
DWG NO. RBST(TOOL# SEE CHART)-(PILOT# SEE CHART)-5	REV A
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	
TOLERANCES ON: DECIMALS .XXX ± .005 .XX ± .01 .X ± .1	FRACTIONS ± 1/32 ANGLES ± 5°
DRAWN BY: PERRITT	
APPROVED	
HEAT TREAT FINISH BLACK OXIDE SPEC USED ON BEARING	
SEE CHART Pg. 1	
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES 015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	
SCALE NTS	DATE 2-14-08
SHEET 4 of 6	




(-3)  
BACK-UP RING  
(2 REQ.)



- NOTES
1.  $\sqrt{125}$  SURFACE FINISH UNLESS OTHER WISE SPECIFIED.

TOOL #	PILOT No.	BEARING		$\varnothing D_1$ +0.003 -0.008	$\varnothing D_2$ +0.015 -0.000	MATERIAL
		OD.	ID.			
1312-055-8-GT	-5015	1.3125	.8750	1.2360	1.562	O-1 DRILL ROD $\varnothing 1-5/8 \times 3/8$


<b>RED BARN MACHINE</b>	
TITLE 8 POINT STAKING TOOL; BACK-UP RING	
DWG NO. RBST(TOOL# SEE CHART)-(PILOT# SEE CHART)-3	REV A
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	DRAWN BY: PERRITT
TOLERANCES ON: DECIMALS .XXX ± .005 .XX ± .01 .X ± .1	APPROVED
FRACTIONS ± 1/32 ANGLES ± 5°	HEAT TREAT RC. 60-63
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES 015 x 45° PR. 015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	FINISH BLACK OXIDE
SCALE NTS	USED ON BEARING
DATE 2-14-08	SEE CHART Pg. 1
SHEET 3 of 6	



TOOL #	PILOT No.	BEARING		ØD <sub>1</sub> + .0003 - .0008	ØD <sub>2</sub>	ØH + .002 - .000	ØH <sub>1</sub>	MATERIAL
		OD.	ID.					
1312-055-8-GT	-5015	1.3125	.8750	1.2360	1.47	.375	-	4140 Q&T Ø1-1/2 x 3

<b>RED BARN MACHINE</b>	
TITLE 8 POINT STAKING TOOL; BODY	
DWG NO. RBST(TOOL# SEE CHART)-(PILOT# SEE CHART)-1	REV A
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	DRAWN BY: PERRITT
TOLERANCES ON: DECIMALS .XXX ± .005 .XX ± .01 .X ± .1	APPROVED
FRACTIONS ± 1/32 ANGLES ± 5°	HEAT TREAT FINISH BLACK OXIDE SPEC USED ON BEARING
UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	SEE CHART Pg. 1
SCALE NTS	DATE 2-14-08 SHEET 2 of 6

REVISIONS				
REV	DESCRIPTION	DATE	INITIAL	APPROVED
A	CH'D T/N FROM KBST.	11/19/09	RJC	

[illegible]

ASSY QTY	ASSY #	B/O	PART #	UNIT QTY	DESCRIPTION	MAT.	B/O INFORMATION OR SPECIFICATIONS	Pg.
			-1	2	BODY	RND. BAR 4140 Q&T	SEE CHART	2
			-3	2	BACK-UP RING	DRILL ROD O-1	SEE CHART	3
			-5	2	RETAINING RING	RND. BAR 4140 Q&T	SEE CHART	4
		W/O	-7	16	PIN		SEE CHART	5
			-9	1	PILOT	RND. BAR 4140 Q&T	SEE CHART	6
		B/O	-11	1	SOCKET HEAD SET SCREW	BLACK	1/4-20 UNC x 1/4	N/S
	ASSY #							

**TITLE** 8 POINT STAKING TOOL;  
ASSEMBLY

**DWG NO.** RBST(TOOL# SEE CHART)-(PILOT# SEE CHART)

**REV** A

UNLESS OTHERWISE SPECIFIED  
DIMENSIONS ARE IN INCHES

TOLERANCES ON:  
DECIMALS  
.XXX ± .005  
.XX ± .01  
.X ± .1

FRACTIONS ± 1/32  
ANGLES ± 5°

UNLESS OTHERWISE SPECIFIED  
1. BREAK ALL SHARP EDGES  
.015 x 45° PR .015 R  
2. DIMENSIONAL LIMITS APPLY AFTER PLATING

**DRAWN BY:** PERRITT

**APPROVED**

**HEAT TREAT** LISTED PER ITEM

**FINISH SPEC** LISTED PER ITEM

**USED ON BEARING**

**SEE CHART Pg. 1**

**SCALE** NTS

**DATE** 2-14-08

**SHEET** 1 of 6

This drawing, specifications, and concepts contained here in are the sole property Red Barn Machine, and may not be reproduced or used in any fashion without the prior written permission of Red Barn Machine.

REVISIONS				
REV	DESCRIPTION	DATE	INITIAL	APPROVED
—	—	—	—	—

NOT APPROVED FOR PRODUCTION

ASSY QTY	B/O PART # UNIT QTY DESCRIPTION MAT.	B/O INFORMATION OR SPECIFICATIONS Pg.
-1	RND	6061 Ø8-1/4 x 3-7/8 2
ASSY #		

TITLE  
8 POINT STAKING TOOL

---

DWG NO.REV

---

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ON:  DECIMALS .XXX ± .005 FRACTIONS ± 1/32 .XX ± .01 ANGLES ± 5° X ± .1	<div>DRAWN BY: PERRITT</div> <div>APPROVED</div> <div>HEAT TREAT FINISH SPEC</div>
--	--

---

UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING	<div>USED ON MODEL</div>
--	--------------------------

---

SCALE NTS	DATE 8-15-07	SHEET 1 of 1
-----------	--------------	--------------

A large, light blue diagonal watermark reading "NOT APPROVED FOR PRODUCTION" spans the entire page, from the top left to the bottom right.

A large, light blue diagonal watermark reading "NOT APPROVED FOR PRODUCTION" spans the entire page, from the top-left to the bottom-right.



This drawing, specifications, and concepts contained here in are the sole property of Red Barn Machine, and may not be reproduced or used in any fashion without the prior written permission of Red Barn Machine.

REVISIONS									
REV	DESCRIPTION					DATE	INITIAL	APPROVE	
—	—						—	—	—

[illegible]

ASSY QTY	ASSY QTY	B/O	PART #	UNIT QTY	DESCRIPTION	MAT.	B/O INFORMATION OR SPECIFICATIONS	Pg.	TITLE
			-1	1	RND	6061	Ø8-1/4 x 3-7/8	2	8 POINT STAKING TOOL; ASSEMBLY
									DWG NO. KBST(TOOL# SEE CHART)-(PILOT# SEE CHART) REV
									UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES
									TOLERANCES ON: DECIMALS .XXX ± .005 FRACTIONS ± 1/32 .XX ± .01 ANGLES ± 5° .X ± .1
									DRAWN BY: PERRITT APPROVED HEAT TREAT FINISH SPEC
									UNLESS OTHERWISE SPECIFIED 1. BREAK ALL SHARP EDGES .015 x 45° PR .015 R 2. DIMENSIONAL LIMITS APPLY AFTER PLATING
									USED ON BEARING SEE CHART Pg. 1
	ASSY #								SCALE NTS DATE 2-6-08 SHEET 1 of 6